



REVISION L


RECOMMENDED BOARD LAYOUT



NOTE: OUTER ROWS MAY NOT NEED VIAS - THIS IS LEFT TO THE DISCRETION OF THE BOARD DESIGNER.



RECOMMENDED STENCIL LAYOUT STENCIL TO BE .0060[0.152] THICK





PROPRIETARY NOTE

HIS DOCUMENT CONTAINS INFORMATION CONFIDENTIAL AND PROPRIETARY TO SAMTEC, INC. AND SHALL NOT BE REPRODUCED OR TRANSFERRED TO OTHER DOCUMENTS OR DISCLOSED TO OTHERS ROUSED FOR ANY PURPOSE OTHER THAN THAT WHICH IT WAS OBTAINED WITHOUT THE EXPRESSED WRITTEN CONSENT OF SAMTEC, INC.



520 PARK EAST BLVD, NEW ALBANY, IN 47150 PHONE: 812-944-6733 FAX: 812-948-5047 e-Mail info@SAMTEC.com code 55322

SHEET SCALE: 4:1

DESCRIPTION:

VITA 42 lif (LEAD FREE) SOCKET ASSEMBLY

DWG NO

ASP-103612-04

F:\DWG\MISC\MKTG\ASP-103612-04-MKT.SLDDRW

BY: RRC

10/13/06

SHEET 2 OF 2